


1/27

Fig.1



2/27

Fig. 2






Fig. 3




3/27

Fig. 4



4/27

Fig. 5



5/27

Fig. 6A




Fig. 6B






Fig. 6C



6/27

Fig.7



10023943 121801

7/27

Fig.8A




Fig.8B






Fig.8C



1003393-121301

8/27

Fig. 9



9/27

Fig.10A





Fig.10B



10/27

Fig.11





Fig.12



11/27

Fig.13





Fig.14



FOSTER "E" 62200T

12/27

Fig.15A




Fig.15B




Fig.15C





FIG. 15A

13/27

Fig.16



10023913 121301

14/27

Fig.17A




Fig.17B






Fig.17C



100391-12101
 108121-16201


15/27

Fig. 18



16/27

Fig.19



17/27

Fig. 20A






Fig. 20B



18/27

Fig. 21



19/27

Fig.22A





Fig.22B



20/27

Fig. 23A





Fig. 23B



21/27




Fig. 24B




Fig. 24A

FOSTER ET AL

22/27

Fig.25






FIG. 25

Fig.26A



24/27

Fig. 27



25/27

Fig. 28




FIG. 28

26/27

Fig. 29





Fig. 30



27/27

Fig.31A




Fig.31B




Fig.31C




FIG. 31A